

At 79.13 chains from "A" and 96.16 Ch. from "G" at "F" The
 Line H.F. Deflects 30' South Running to Township Corner at G
 L.A.F. — The lap from "D" to "F" is made 2.24 chains instead
 of 1.47 chains for reasons stated in "note"
 "F" is witnessed: Bur Oak 5" S 15° W 88 Links W Oak 7" N 88½° E 187
 This is the same white Oak used as witness for "II"
 "F" now stands 81.04 chains from "H"

"K" In as much as Joel Pendleton County Surveyor for
 Hancock Co Ohio did in September 1865 made a
 resurvey of Sections 31 & 32 S R 12 E, and did so subdivide
 it as to make the quarter post to Section 31 & 32
 take the middle point of the line between said sections
 And as such a point now tallies exactly with the
 Old fence line: The quarter post between said sections
 in this survey is placed at the middle point of the
 Line at K = But 39½ links west of a straight line
 from H to F. There is a deflection in this line of 33½'
 To the East from K to F = From line from H to K

"K" is marked by a stake 2 inches square and stands about
 9 links south of small open ditch and about 20 links
 south of fence as rebuilt
 Witnessed Bur Oak 12 S 84° E 57 links Cluster of Ash from 6" to 4"
 in Diameter S 10° E 13 links
 Our Survey between Sections 5 & 6 T 3 S R 12 E substantiates
 The Present Location of "D"

Surveyed By: *R. B. Dugan* Surveyor of Wyandot County O.
O. P. Wilson " " Hardin " "
John W. B. Reigle " " Hancock " "

J. Q. Merrick Upper Sandusky Ohio }
E. C. Bolton Findlay Ohio } Chairmen