

1. Bm Oak. 6 in S 23 1/4 E 18 put NW 1/4 N.E 1/4 S.E 1/4 to S.W. 1/4 S.E
do 8 N 4 1/2 W 12 Y 1. S 12 13 E

Frederick Shoeman Oct 24. 1848

TAX MAP COPY

V


1/4	07576
3.94	5.94
1.560	8.50
3.94	8.50
3.94	8.50

NW Corn N.E. 1/4 Sec 12 T2 R13 E

1. Hiding 8 in S 1 1/4 E 10 1/2 W oak 15 in N 22 1/2 E 26

John A. Munter Oct 25. 1848

TAX MAP COPY



- At 1. Cross Creek in N 87 E 12.3
2. Burying 10 in N 78 E 9 Immovable in S 24 E 12
3. Burying 14 in D 69 1/2 W 23 1/2 W. Oak 36 in N 68 1/2 E 61
4. W. Oak 12 in D 47 E 64 W. Oak 24 in D 69 E 65 1/2