


TAX MAP COPY



Sec 12 T. 3 N. R. 14 E.

Surveyed March 2. 54 6 1866 for  
No 105 John Matthias No 106 John Tiffenbarger

No 107 John Liniger No 108 Peter Rieder

No 109 Ch. Gerhardt No 111 Jacob Troy

No 112 John Barth No 113 & 114 William Smalley

No 115 John Burden No 116 Ch. Braun

No 117 & 120 Ch. Barth No 118 Christian Kiedersamer


No 119 Henry Schichtel

at center of Section 12


N 0° 0' 10" 35" W 2 1/4

Survey 12 N 6 3/4 W 48 3/4

ORIGINAL COPY




TAX MAP COPY



$E \frac{1}{2} S W \frac{1}{4} S. 6. T. 1 S. R. 14 E$

Surveyed March 30<sup>th</sup> 1866 for George Luckman

TAX MAP COPY



N. E. corner of N. E. 1/4 S. 3 T. 14 E.  
Surveyed April 11<sup>th</sup> 1866 for  
Henry Jones