

SURVEY № 816

$663.25'$
E.C.H. 662
N¹/₄ Stone
Sec. 29-T35-R13E
Mifflin Tp.

$5.88^{\circ}-55'E.$

396'

NOTE -
IN MAKING THIS SURVEY IT
WAS MUTUALLY UNDERSTOOD WITH
ABUTTING PROPERTY OWNERS THAT
EXISTING FENCE LINES AS SHOWN
WERE THE CORRECT PROPERTY
LINES.

N.

$N. 1^{\circ}-30'E.$

$135.26'$

$800.95'$

$S. 1^{\circ}-30'W.$

I CERTIFY THIS TO BE A
TRUE AND CORRECT PLAT OF
SURVEY MADE BY RAY H. HEHR
& ASSOCIATES IN OCT. 1948

(Sig) Ray H. Hehr
REGISTERED SURVEYOR
№ 1159

$N. 86^{\circ}-44'E$

372.50'

Part of N²NE⁴
Sec. 29, T35, R13E
16.33[±] A. 111.44 L.R.

PLAT OF SURVEY OF LAND
MEASURED ON SITE FOR
MAMIE BEAMER OCT. 1948

$614'$

$N. 88^{\circ}-8'W.$

$56^{\circ}-5'E$

$50'$

$128.80'$

$584^{\circ}-9'W.$

$112^{\circ}-13'$

$112^{\circ}-13'$

$128.80'$

$584^{\circ}-9'W.$

$112^{\circ}-13'$

$128.80'$

$584^{\circ}-9'W.$