


PITT  
26-3-14

TAX MAP COPY

VOL. 5  
PG. 72

72

SURVEY N<sup>o</sup> 1928 ✓



SURVEY FOR HOWARD RIESER


1" = 200' == SPIKE O = IRON PIPE  
PT. W 1/2 SW 1/4 SEC. 26, T3S, R14E  
PITT TWP., WYANDOT CO., OHIO  
BY JERRY B. WEININGER  
OHIO REG. SURV. NO 5647  
DATE OCT. 1978

CRAWFORD  
4-1-13

VOL. 5  
PG. 72

TAX MAP COPY

SURVEY NO 1929 ✓



SURVEY FOR PAUL WONDER

SCALE 1" = 200' \* = SPIKE O = IRON PIPE

PT E 1/2 NE 1/4 SEC. 4 T. 15 R. 13 E

CRAWFORD TWP. WYANDOT CO., OHIO

BY JERRY B. WEININGER


OHIO REG. SURV. NO 5647

DATE SEPT. 1978

TAX MAP COPY

SURVEY No 1930 ✓

SURVEY FOR RICHARD SHELLHORN



SCALE 1" = 100' = SPIKE O = PIPE  
PT E 1/2 NE 1/4 SEC. 13 T. 15S, R. 14E  
TYMOCHTEE TWP. WYANDOT CO., OHIO  
BY JERRY B. WEININGER  
OHIO REG. SURV. NO 5647  
DATE OCT., 1978