





at 1. Hickory 10' N 20 1/4 E 21. Book 15 1/2 1842 N 35
2 Book 20 1/2 N 57 1/2 33



Sandy River

At 8.00 N. 17 1/2 W. 1/4 . of NW 1/4 Sec 26 T3 S R 14 E

Surveyed June 7. 1880

Joab Simons

At 1. Elm 14 1/2 N 35 W 8 1/2 B Walnut 4 1/2 N 34 E 4 1/2 At 2. Spruce 16


South 98 = at 3 N. 00 1/2 E 12 1/2 S 70 1/4 E 14 Red Oak 12 1/2 S 15 1/2 E 16

At 4. Hickory 6 North 10 Spruce 15 S 3 W 20. at 5. Birch 10

S 49 E 9 Hickory 6 N 68 W 9 1/2

Survey No 766. Commencing at a corner N. W. for the
Meeting House in the Town of Ware. Beginning then
N 41 W. 12.88. then S 87 W 2.82 then S 17 W 10.92
then N 86 1/4 E 8.87. then N 86 1/4 E 5.63. - A 8.89
pt. S 1/2 N E for 1/4 S 1. S. S 12 1/4 E.
Thomas Boyes, Sw. February 1850

TAX MAP COPY



N.E. pt of $\frac{1}{2}$ NW $\frac{1}{4}$ S 78. T2 S R 15 E
E.C. G. Schubert, March 21. 1837

1. At l. W. o. h. Stop 48 S 80 W 79. Thence Stop 36 N 4 E 45
2. Thence o. h. 80 N 13 E 71 W. o. h. 6 N 9 W 84
3. Thence o. h. 10 S 8 E 40 W. o. h. 10 S 24 E 28 in. S. o. h.